



A surface marking tool for suitable cosplay materials to be used with any common marking device. Can be set from 1/8" to 7" (3mm to 18cm) borders and accept marking devices up to 1/2" thick. Trace perfect lines at a specific distance around the outer edge of your cosplay.



HOW TO USE

- 1 Insert a marking device. Insert a pencil, pen, or marker upto 1/2" in diameter into the Marker Holder (**Fig. 1**).
- 2 Adjust the marker to your desired height and then tighten the thumb screw to lock in place (**Fig. 2**).
- 3 Adjust the Measuring Block to your desired border dimension. Read the scale to the inside of the Measuring Block (side closest to the marker) for accurate border width (**Fig. 3**).
- 4 Align the Measuring Block pins against the edge of your cosplay material. Press marker tip onto the material and pull along the edge (**Fig. 4**).

NOTE: There are many different ways to hold the tool while marking your material - try to find a way that works best for you. We suggest laying the material on a table while the edge you want to mark hangs over its edge.



Fig 1




Fig 2




Fig 3




Fig 4

*Marking devices are not included